

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® Long Sleeve Easy Care, Soil Resistant Shirt. S607

Product photo



A carefree work shirt you'll actually enjoy wearing. The wrinkle-resistant fabric keeps you looking sharp, while the soil-release treatment protects you from stains. All this—at a tremendous value!

- 3.7-ounce, 60/40 cotton/poly with soil-release finish
- Button-down collar
- Dyed-to-match buttons
- Patch pocket
- Button-through sleeve plackets
- Adjustable cuffs

CARE INSTRUCTIONS

Machine wash cold with like colors. Do not bleach. Do not dry clean. Tumble dry low. Warm iron if necessary.

Sketches



front



back

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL
Body Length at Back	26 1/2	28 1/2	31	31 1/2	33	33 1/2	34 1/2	35	35 1/2	36
Chest	20	21 1/2	23	24 1/2	26	27 1/2	29	30 1/2	35 1/2	37
Neck	15 1/2	16	16 1/2	17	17 1/2	18	18 1/2	19	19 1/2	20
Pockets	5 x 5 1/2	5 x 5 1/2	5 1/4 x 6	5 1/4 x 6	5 1/4 x 6	5 1/4 x 6	5 1/2 x 6 1/4	5 1/2 x 6 1/4	5 1/2 x 6 1/4	5 1/2 x 6 1/4
Sleeve Length	31	32 1/2	34 1/2	35 1/2	37	38	39	40	41	42

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Neck: Measured from center of button to center of buttonhole.


Pockets: Multiply width by height of pocket.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL	7XL	8XL	9XL	10XL
Arm	30 1/2	32	34	35	36 1/2	37 1/2	38 1/2	39 1/2	40 1/2	41 1/2	41 1/2	41 1/2	41 1/2	41 1/2
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57	58-60	61-63	64-66	67-69	70-72	73-75
Neck	14 1/2	15	15 1/2	16	16 1/2	17	17 1/2	18	18 1/2	19	19 1/2	20 1/4	20 3/4	21 1/4
	-	15	-	16	-	17	-	18	-	19	-	-	-	-
	15	1/2	16	1/2	17	1/2	18	1/2	19	1/2	20 1/4	20 3/4	21 1/4	21 3/4

HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

COLORS



Faded Blue
PMS 7684 C



Light Stone
PMS 454 C



Navy
PMS 533 C



White