

SPEC SHEET + MEASUREMENTS



Hanes® X-Temp® T-Shirt. 4200

Product photo



- 4.5-ounce, 60/40 ring spun cotton/poly
- 90/10 cotton/poly (Light Steel)
- Softest hand in performance
- 40+ UPF rating
- Moisture wicking with dynamic vapor control
- Tear-away label
- Double-needle coverseamed neck
- Contrast neck taping
- 3/4" lay-flat collar
- Shoulder-to-shoulder taping
- Double-needle sleeves and hem

Please note: This product is transitioning from tag-free labels to tear-away labels. Your order may contain a combination of both.

CARE INSTRUCTIONS

Turn inside out, machine wash cold, remove promptly after wash. Only non-chlorine bleach when needed. Tumble dry low. Cool iron if needed. Do not dry clean or use fabric softener.

Sketches



front



back

SPEC SHEET + MEASUREMENTS



Hanes® X-Temp® T-Shirt. 4200

PRODUCT MEASUREMENTS

	S	M	L	XL	2XL	3XL
Chest	18	20	22	24	25 3/4	28
Body Length at Front	27 3/4	28 3/4	29 3/4	30 3/4	31 3/4	32 1/4
Sleeve From Shoulder	16 1/4	17 1/8	18 1/8	19 1/8	20 1/8	20 5/8

Chest: Measured across the chest one inch below armhole when laid flat.

Body Length at Front: Measure from high point shoulder to lowest point of hem at front.

Sleeve From Shoulder: Measured from high point of shoulder to finished hem at sleeve.

SIZE CHARTS


	S	M	L	XL	2XL	3XL	4XL
Chest	34-36	38-40	42-44	46-48	50-52	54-56	58-60

SPEC SHEET + MEASUREMENTS



Hanes[®] X-Temp[®] T-Shirt. 4200

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.