SPEC SHEET + MEASUREMENTS

PORT AUTHORITY.

Port Authority® C-FREE® Rain Jacket. J714

Product photo



Designed to shrug off wet conditions, this carbon-reducing C-FREE jacket helps keep you drier and little more sustainable.

- 100% recycled polyester shell and lining
- This product's carbon footprint has been measured and reduced through a combination of preferred materials and investing in carbon offset projects though the ClimeCo
 Certified Product[™] Program
- Fabric waterproof rating: 8000MM
- Fabric breathability rating: 5000G/M²
- · Attached, adjustable hood
- Full-length exterior storm flap with hidden snaps
- Hidden zippered pockets
- Adjustable hook and loop tabs at cuffs
- · Adjustable locking drawcord at slight drop tail hem
- Port Pocket[™] for decoration access
- Water protection method: water-resistant finish, fully seamsealed

Sketches



front



back

A C-FREE® Product

We start by reducing the product's impact by switching to at least 50% preferred materials. We then measure and reduce the total carbon footprint of each product in the C-FREE program—from cradle-to-grave—through the ClimeCo Certified Product[™] Program. This certification purchases third-party, verified carbon offsets through ClimeCo.

CARE INSTRUCTIONS

Machine Wash Cold. Do Not Bleach. Cool Iron If Needed. Do Not Dry Clean.

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY.

Port Authority® C-FREE® Rain Jacket. J714

PRODUCT MEASUREMENTS

	xs	S	М	L	XL	2XL	3XL	4XL
Body Length at Back	26	27	28	29	30	31	31 1/2	32
Chest	19 1/4	20 3/4	22 1/4	23 3/4	25 1/4	26 3/4	28 3/4	30 3/4
Sleeve Length from Center Back	34 3/4	35 1/2	36 1/4	37	37 3/4	38 1/2	39 1/4	40

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

SIZE CHARTS


	xs	S	М	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY.

Port Authority® C-FREE® Rain Jacket. J714

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

COLORS



Deep Black PMS BLACK



Grey Steel



Rich Red PMS 207C



True Navy PMS 533C



True Royal PMS 7687C