

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® C-FREE® Core Soft Shell. J720

Product photo



Thanks to a 100% recycled polyester shell, our popular Core Soft Shell just became more sustainable.

- 100% recycled polyester shell
- 100% polyester brushed microfleece lining
- This product's carbon footprint has been measured and reduced through a combination of preferred materials and investing in carbon offset projects through the ClimeCo Certified Product™ Program
- Fabric waterproof rating: 1000MM
- Fabric breathability rating: 1000G/M²
- Reverse coil zippers
- Right chest zippered pocket
- Front zippered pockets
- Open cuffs and hem
- Water protection method: Laminate film and water-resistant finish

Sketches



front



back

A C-FREE® Product

We start by reducing the product's impact by switching to at least 50% preferred materials. We then measure and reduce the total carbon footprint of each product in the C-FREE program—from cradle-to-grave—through the ClimeCo Certified Product™ Program. This certification purchases third-party, verified carbon offsets through ClimeCo.

CARE INSTRUCTIONS

Machine Wash Cold. Do Not Use Fabric Softener. Only Non-Chlorine Bleach, When Needed. Tumble Dry Low. Cool Iron, If Necessary. Do Not Dry Clean.

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® C-FREE® Core Soft Shell. J720

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	26 1/2	27 1/2	28 1/2	29 1/2	30 1/2	31 1/2	32	32 1/2
Chest	19 3/4	21 1/4	22 3/4	24 1/4	25 3/4	27 1/4	29 1/4	31 1/4
Sleeve Length from Center Back	34 5/8	35 1/4	35 7/8	36 1/2	37 1/8	37 3/4	38 1/2	39 1/4

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

SIZE CHARTS


	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® C-FREE® Core Soft Shell. J720

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

COLORS



Deep Black
PMS BLACK
C



Grey Steel



True Navy
PMS 533C



True Royal
PMS 7687C