

SPEC SHEET + MEASUREMENTS



OGIO® Quarry Jacket. OG505

Product photo



With its doobby texture and high-performance look, this water-resistant jacket takes a stand against the elements.

- 100% poly doobby
- Zip-through cadet collar with rib knit
- OGIO heat transfer label for tag-free comfort
- Rubber OGIO detail on center back waist inner liner
- Rubber O detail at back neck
- Metalux zipper with rubber OGIO zipper pull
- Zippered right chest pocket with rubber OGIO zipper pull
- Zippered front pockets with rubber O zipper pulls and OGIO rivets
- Rib knit, self-fabric open cuffs and hem

CARE INSTRUCTIONS

Machine wash cold with like colors. Gentle cycle. Non-chlorine bleach only as needed. Tumble dry low. Use low iron. Do not dry clean.

Sketches



front



back

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	27 1/2	28	28 1/2	29	30	31	31 1/2	32
Chest	19 1/2	21	22 1/2	24	25 1/2	27	29	31
Sleeve Length	35 1/4	36	36 3/4	37 1/2	38 1/4	39	39 3/4	40 1/2

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.