

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY.

Port Authority® Non-Iron Twill Shirt. S638

Product photo



With the same non-iron finishing treatment as more expensive brands, our non-iron twill shirt helps you keep your sharp looks —at a real value. Crafted from special 40-singles compacted yarn for enhanced softness and comfort, this shirt will keep you professional looking long past five o'clock.

- 4-ounce, 100% cotton
- Pucker-free taped seams
- Open collar with stays
- Dyed-to-match buttons
- Back box pleat
- Left chest pocket
- Rounded adjustable cuffs

CARE INSTRUCTIONS

Machine wash warm with like colors. Do not bleach. Tumble dry low. Remove promptly and hang.

Sketches



front



back

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® Non-Iron Twill Shirt. S638

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	29	30	31	32	33	34	34 1/2	35
Chest	20	21 1/2	23	24 1/2	26	27 1/2	29 1/2	31 1/2
Neck	16 1/2	16 1/2	17	17 1/2	18 1/2	19 1/4	20	20 3/4
Pocket Height	5 1/4	5 1/4	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 3/4
Pocket Width	4 3/4	4 3/4	5	5	5	5	5	5 1/4
Sleeve Length	33 3/4	34 1/2	35 1/4	36	36 3/4	37 1/2	38 1/4	39

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Neck: Measured from center of button to center of buttonhole.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

SPEC SHEET + MEASUREMENTS


PORT AUTHORITY

Port Authority® Non-Iron Twill Shirt. S638

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Arm	30 1/2	32	34	35	36 1/2	37 1/2	38 1/2	39 1/2
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57
Neck	15 1/2	16	16 1/2	17	17 1/2	18	18 1/2	19

HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

COLORS



Green Mist
PMS 580 C



Light Stone
PMS 454 C