## **SPEC SHEET + MEASUREMENTS**



Brooks Brothers® Tall Wrinkle-Free Stretch Pinpoint Shirt. TBB18000

## **Product photo**



This iconic dress shirt combines a little bit of stretch with a higher back yoke for a classic fit. A premium wrinklefree treatment process means effortless style and a sharp, professional finish all day long.

- 4.4-ounce, 97/3 cotton/spandex fine yarn count
- Taped seams
- Button-down collar
- Left chest pocket
- · Pearlized buttons
- · Rounded, single-button cuffs
- Rental-friendly

### CARE INSTRUCTIONS

Machine Wash Warm With Like Colors. Only Non-Chlorine Bleach If Needed. Tumble Dry Low. Remove Promptly And Hang. Warm Iron If Needed.

## **Sketches**







back

# SPEC SHEET + MEASUREMENTS



Brooks Brothers<sup>®</sup> Tall Wrinkle-Free Stretch Pinpoint Shirt. TBB18000

#### PRODUCT MEASUREMENTS

	LT	XLT	2XLT	3XLT	4XLT
Body Length at Back	33	33 1/2	34	34 1/2	35
Chest	24	26	28	30 1/2	33 1/2
Sleeve Length from Center Back	37 1/2	38 1/4	39	39 3/4	40 1/2
Neck Circumference	17 1/2	18 1/4	19	19 7/8	20 7/8
Chest Pocket Height	5	5	5	5	5 1/4
Chest Pocket Width	4 5/8	4 5/8	4 5/8	4 5/8	4 7/8

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

Neck Circumference: Measure from center of button to end of buttonhole along the center of the collar stand.

Chest Pocket Height: Measure from top to bottom at center.

## **SPEC SHEET + MEASUREMENTS**




Brooks Brothers<sup>®</sup> Tall Wrinkle-Free Stretch Pinpoint Shirt. TBB18000

## SIZE CHARTS

	LT	XLT	2XLT	3XLT	4XLT
Chest	41-43	44-46	47-49	50-53	54-57
Neck	16 - 16 1/2	16 1/2 - 17	17 - 17 1/2	17 1/2 - 18	18 - 18 1/2
Arm	36 1/2	38	39	40	41

## HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base.

Chest Width Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. Arm Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

## **COLORS**









Cobalt Blue

Deep Black PMS BLACK Newport Blue PMS 7681C White