# SPEC SHEET + MEASUREMENTS



## Wink® Men's Consultation Lab Coat. WW5072

### **Product photo**




- 65/35 poly/cotton poplin
- Locker loop
- Left chest pocket with pen slot
- Top-loading front pockets
- Interior tablet pocket
- · Back yoke with pleats
- · 3-button placket opening
- · Center back vent
- Wink® heat transfer logo at left pocket
- Size medium: 31.5-inch back length

### **CARE INSTRUCTIONS**

Machine Wash Cold With Like Colors. Gentle Cycle. Use Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Remove Promptly From Dryer. Cool Iron When Needed.

#### **Sketches**



# SPEC SHEET + MEASUREMENTS



Wink® Men's Consultation Lab Coat. WW5072

#### PRODUCT MEASUREMENTS

	xs	S	M	L	XL	2XL	3XL	4XL	5XL
Body Length at Back	30 1/2	31	31 1/2	32	32 1/2	33	33 1/2	34	34 1/2
Chest	42	45	48	51	54 1/2	58 1/2	62 1/2	66 1/2	70 1/2
Set in Sleeve Length	23 7/8	24	24 1/8	24 1/4	24 3/8	24 1/2	24 5/8	24 3/4	24 7/8
Pocket Height	5 1/2	5 1/2	5 1/2	6	6	6	6 1/2	6 1/2	6 1/2
Pocket Width	5	5	5	5 1/2	5 1/2	5 1/2	6	6	6

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Set in Sleeve Length: Measure from Center Back neck to shoulder point to sleeve hem.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

#### SIZE CHARTS


	xs	S	М	L	XL	2XL	3XL	4XL	5XL
Chest	34-35	36-38	39-41	42-45	46-49	50-53	54-57	58-60	61-64

# SPEC SHEET + MEASUREMENTS



Wink® Men's Consultation Lab Coat. WW5072

#### HOW TO MEASURE



#### **CHEST**

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

### **COLORS**

White