

SPEC SHEET + MEASUREMENTS



Wink® Men's Long Lab Coat. WW5172

Product photo



- 65/35 poly/cotton poplin
- Locker loop
- Left chest pocket with pen slot
- Top-loading front pockets
- Interior tablet pocket
- Side seam opening for easy access to pants pockets
- Back yoke with pleats
- 4-button placket opening
- Center back vent
- Wink® heat transfer logo at left pocket
- Size medium: 42-inch back length

CARE INSTRUCTIONS

Machine Wash Cold With Like Colors. Gentle Cycle. Use Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Remove Promptly From Dryer. Cool Iron When Needed.

Sketches



front



back

SPEC SHEET + MEASUREMENTS



Wink® Men's Long Lab Coat. WW5172

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL	5XL
Body Length at Back	41	41 1/2	42	42 1/2	43	43 1/2	44	44 1/2	45
Chest	42	45	48	51	54 1/2	58 1/2	62 1/2	66 1/2	70 1/2
Set in Sleeve Length	23 7/8	24	24 1/8	24 1/4	24 3/8	24 1/2	24 5/8	24 3/4	24 7/8
Pocket Height	5 1/2	5 1/2	5 1/2	6	6	6	6 1/2	6 1/2	6 1/2
Pocket Width	5	5	5	5 1/2	5 1/2	5 1/2	6	6	6

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Set in Sleeve Length: Measure from Center Back neck to shoulder point to sleeve hem.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

SIZE CHARTS


	XS	S	M	L	XL	2XL	3XL	4XL	5XL
Chest	34-35	36-38	39-41	42-45	46-49	50-53	54-57	58-60	61-64

SPEC SHEET + MEASUREMENTS



Wink[®] Men's Long Lab Coat. WW5172

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

COLORS



White